

202, Bonny Apartment, Arunoday Society, Alkapuri, Nr. Alkapuri Post Office, Vadodara 390 007. Ph.: + 91 - 265-2351766 + 91 - 99250 28642 Email: info@brpa.co.in Website: www.brpa.co.in

## STRUCTURAL STABILITY CERTIFICATE

I hereby certify that I had inspected the AnandalayaSchool managed by Anandalaya Education Society (AES)at Anand, Dist. Anand, in the state of Gujarat with a view to ascertain the structural stability of the building. The structural elements inspected include column, beam, slab, staircase etc. at each floor. The observations indicate absence of distress and any kind of deterioration in all RCC elements.

I have also carried out number of NDT tests to estimate present strength of all RCC elements with reference to strength and quality of concrete and steel reinforcement detailing. NDT test results indicate acceptable strength and quality of concrete and adequate steel reinforcement in all RCC elements.

I have gone through the structural drawings available for the existing structure, physically verified actual provisions in RCC elements at site in accordance with drawing and evaluated structural stability with the help of licensed software.

I hereby certify that this school building structural work is safe and suitable for use in the present loading condition as on today. However, structural stability cannot be ensured in the event of act of god.

B R PATEL ASSOCIATES VADODARA.